

Friday, 13/06/2008 8:56:43 AM
Linda Lacelle

Process Sheet

Customer	: CC-DAR01 Dart Aerospace Ltd.		Drawing Name	: D412-698-011	
Job Number	: 39850		Part Number	: REWORK30	
Estimate Number	: 10804		Drawing Number	: DISASSEMBLE	
P.O. Number	:		Project Number	:	
This Issue	: 13/06/2008		Drawing Revision	:	
Prsht Rev.	: NC		Material	:	
First Issue	: //		Due Date	: 20/06/2008	
Previous Run	: 00015		Qty:	2	Um: Each
Written By	:				
Checked & Approved By	:				
Comment	:				

Additional Product

Job Number:



Seq. #:	Machine Or Operation:	Description:	
1.0	PACKAGING 1	PACKAGING RESOURCE #1	
<p>Comment: PACKAGING RESOURCE #1 PULL FROM STOCK:</p> <p>1 X D412-698-011 B <u>39006</u></p> <p>REMOVE 2 X D3183-043 B <u>(OE 63262)</u> <u>2 37072x2</u></p> <p>RETURN 2 X D3183-043 B <u>370721X</u></p> <p>WHEN AVAILABLE</p>			
2.0	D3183043	Bracket Assembly	
<p>Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s) Bracket Assembly</p> <p><u>370721X B 39862 1X 1/28/08</u></p>			
3.0	QC4	INSPECT 100% KITS FOR COMPLETENESS	
<p>Comment: INSPECT 100% KITS FOR COMPLETENESS</p> <p><u>808/2/28/08</u></p>			
4.0	PACKAGING 1	PACKAGING RESOURCE #1	
<p>Comment: PACKAGING RESOURCE #1</p> <p>REPACKAGE PER PPP USING ORIGINAL B/N</p> <p><u>Rev B</u> <u>808/07/29</u> <u>(X)</u></p>			

Process Sheet

.er: CC-DAR01 Dart Aerospace Ltd.

Drawing Name: D412-698-011

J Number: 39850

Part Number: REWORK30

J Number:




Seq. #:	Machine Or Operation:	Description :
5.0	QC21	FINAL INSPECTION/W/O RELEASE

Comment: FINAL INSPECTION/W/O RELEASE



D08105108

Job Completion



u 08/08/01